


(i) indesit



Model type: TVM63XNA

Commercial code: F063076









General notes

Technical Documentation guidelines	

You can find herewith some generic information to simplify cunsulting of technical documentation:

- 1. Models of same range share the same exploded views, which report the richest set of spare parts:generally, a model does not necessarly have a related spare part for each particular shown on exploded views.
- 2. Some spare parts can not be represented directly on the exploded views (instruction booklets, specific kit, etc...). You can find those codes in the spare parts list with the same reference of particular where spares are installed or with references 099, 999. Instruction booklets, once managed, appear with 000 reference.
- 3. On the higher right site of each exploded view there is a serial number which indicates the beginning of the production of certain range:some models might have more than an exploded view for a given category, each distinguished by a different serial no and linked to another spare parts list, In this case, serial no is required to supply the right spare part code. Exploded view to be considered is the one with a more recent serial no. but previous than the one of the model that needs assistance.
- 4.Exploded views might require further updates even after publishing. Addition of new spares will go on following the already existing numeration references. Revision number of an exploded view is shown into last four digits of serial number into upper right hand corner.
- 5. The spare parts list associated to an exploded view shows related codes of spares managed for a certain model; for each spare part other informations are available:

REF: reference no of spare into a table; SUBSTITUTE: list of spare(s) which can replace a code but that keeps same functional characteristics

INDUSTRIAL CODE: list of variables of a model (shown into model label) where such spare is used; NOTICE: code of information(s) to refer to complete technical intervention, track for changes or to find correct spare part code.


- 6. Some notices, into a same section are generic therefore cannot be directly linked to a spare part. In order to assist a model in the best way as possible, it is helpful to pay attention to all notices and constantly verify documentation updates
- 7. Technical documentation cover shows model name and its commercial codes





page 3

07303-20 Exploded views



mod.TVM63XNA





07303-20 Spare parts list


Ref.	Code	From	To S/N	Substitute	Description	Notice	Industrial			
401	C00142621			1 x C00292290 base panel ul						
401	C00252668			bracket						
404	C00142775			adjustable foot ul						
405	C00142623				motor 353 60hz 120v					
408	C00142624				motor capacitor 25uf ul					
409	C00112153				impeller-inner					
410	C00116327				fan-outer					
420	C00145648				rear seal 17mm					
421	C00145707				stretch belt h9 1860mm (td)					
422	C00268493			1 x C00268492	drum vent td st/ul fixed shaft					
423	C00142627				rear panel ul					
424	C00142628			drum rear bearing teardrop						
424	C00250889			screw						
425	C00142631			drum shaft collar						
426	C00095551			drive pin						
427	C00192903			this item is not fitted to this model						
428	C00192903			this item is not fitted to this model						
429	C00142632				vent hose adaptor ul					
430	C00142633		10107		heater 1.32kw usa	n4411a00				
430	C00283154	10108			heater 1.32kw usa + columbo	n4411a00				
432	C00142635				thermostat kit					
445	C00142636				mains plug assembly usa ul					
450	C00112184			side panel phd white						
452	C00095553				rear bearing cover					
463	C00142638			1 x C00290730 drum lifter ul n4412c01						
463	C00290730			drum lifter short curved ul (usa) n4412c01						
468	C00142639			reversing timer 120v usa						
483	C00142651				terminal block 120v					
491	C00122256				screw 6 x 3/8					
491	C00260451				brace					
999	C00142716				belt installing tool dryer gda					





page 5

07430-05 Exploded views








07430-05 Spare parts list

Ref.	Code	From	To S/N	Substitute	Description	Notice	Industrial	
000	C00280677			kit connection w lvb-dryers vented n1040357				
101	C00275200		console panel tvm63xna ul					
103	C00195542		compression ring					
103	C00275188		programme knob ul					
107	C00275199		button white ul					
111	C00095500		switch					
112	C00142602		start switch					
113	C00142608		00107 timer mounting plate 95630760000					
113	C00255416	00108	31201 timer bracket 9563076000				95630760000	
113	C00270858				timer crouzet 120v 60hz			
113	C00304976	31202	timer bracket 95630760100				95630760100	
125	C00275197		worktop white ul					
147	C00275198				button white ul			





07441-17 Exploded views







07441-17 Spare parts list

Ref.	Code	From	To S/N	Substitute	Description	Notice	Industrial		
201	C00142609			kick strip white ul					
205	C00270779			filter round f/panel hb/ul					
206	C00303464	31202			thermostat one shot 85'c		95630760100		
207	C00142612		31201		vent tube ul		95630760000		
207	C00303457	31202			vent tube ul (metal)		95630760100		
209	C00142613				drum front seal 14mm				
209	C00276750				seal drum front 16mm vented	n4409k00			
210	C00252668				bracket				
210	C00261883			front panel white					
211	C00208247			eco stat 40'c					
212	C00112211			door seal vented grey n4411g01					
212	C00286379			door seal vented white n4411g01					
213	C00112144			bearing pad					
215	C00275218				door switch unit (td) ul				
221	C00275219				door trim - front white ul				
222	C00142617		31201		door trim rear white ul		95630760000		
222	C00304419	31202			door trim rear white ul		95630760100		
223	C00112192				door bowl				
224	C00254619				hinge				
233	C00142619				door latch (td)				
257	C00270778				air duct round vent hb/ul				
266	C00303464	31202			thermostat one shot 85'c		95630760100		
999	C00277631				service manual				





Notices

n1040357: Fixing	bracket for	installing	Dryers on	Washing	Machines

The spare part KITS for installing the Dryers affected by this note on Washing Machines are the following:

The space part 11770 for instanting the 217 etc affected by this note on Washing Machines are the 1010 mig

- Spare part code C00115839 KIT for VENTED DRYERS WHITE
- Spare part code C00114866 KIT for CONDENSER DRYERS WHITE
- Spare part code C00149478 KIT with SHELF for CONDENSER/VENTED WHITE
- Spare part code C00280677 (exC00142690) KIT VENTED DRYERS USA 2010 white
- Spare part code C00280679 KIT VENTED DRYERS USA 2010 SILVER
- Spare part code C00280681 (exC00142830) KIT CONDENSER DRYERS USA 2010 white
- Spare part code C00280680 KIT CONDENSER DRYERS USA 2010 SILVER

n4411a00: USA VENTED HEATER CHANGES

FROM SERIAL NUMBER 10108.0000 A NEW HEATER WITH A COLOMBO CONNECTOR HAS BEEN USED IN PRODUCTION.

THIS NEW HEATER IS NOT INTERCHANGEABLE WITH THE PREVIOUS ONE.

SEE PARTRS LIST FOR CORRECT PART.

n4411g01: VENTED DOOR SEALS

ON SELECTED TUMBLE DRYERS FROM JUNE 2011 THE DOOR SEAL COLOUR CHANGED FROM GREY TO WHITE.

n4412c01: VENTED TUMBLE DRYER DRUM LIFTER

From Sept 2011, a curved drum lifter, has been used in production, the new lifter is fully interchangeable with the original straight drum lifter, once stock of the straight drum lifter is exhausted, the curved drum lifter will become the Service Spare, for all production dates".

n4409k00: FRONT AIR DUCT & AIR DUCT SEAL

FRONT AIR DUCT SEAL

Both 14mm and 16mm Air Duct Seals have been used in production.

14 mm - used Before Serial No. 50501.0000 (May 2005)and After 00107.0001 (July 2010)

16 mm - used Between Serial No.s 50501.0001 (May 2005) and 00107.0000 (July 2010) - See note below

If replacing only the Seal - select the CORRECT size from the parts list.

AIR DUCT

White Air Ducts were used in production from 10601.0000 (June 2011), the only difference to the Grey Ducts is the colour change.

WHITE AIR DUCTS ONLY will become the only Service Air Duct Once Stock of the Grey Air Ducts is exhausted If the original air duct is grey, the air duct kit is required which includes a white filter.

NOTE: ALL SERIAL NUMBERS:


If the AIR DUCT is being replaced you will require a 14mm Seal because the service replacement AIR DUCT is 14mm. See parts List





Electric schemes and links

Cod. 5407787







Legend


Legend: 5407787





Electric schemes and links

Cod. 5407788







Legend

Legend: 5407788